



**Quick Reference Card** Trimble XCN2050/TMX2050 Beacon 4 Installation & Set-up

Cable Installation

Mounting

1

Install the Beacon into the EXP-100 port expander cable

- 1. Use 3 screws supplied with kit and attach Beacon 4 to tapered part of bracket. Don't overtighten.
- 2. Use supplied alcohol swabs to clean a small section of the tractor roof.
- 3. Peel back the mounting plate adhesive strips and press onto roof.
- 4. The bracket will then magnetically mount to base plate.

## Note: Beacon 4 must be mounted vertical.



0 0

Pair your Beacon 4.0 with the GR Tech NBV1 NTRIP Client iOS App. Once paired your iPad will ask to download directly from the Apple App Store. See our App QRC for set-up details.



Continue installation on back page



1

Technical Support 319.531.7574 support@digifarm.com

> Part #BN4000-32 Product Store Link

> > 2

5



On the GPS Receiver setup page change the Corrections to CenterPoint RTK **Quick Reference Card** Trimble XCN2050/TMX2050 Beacon 4 Installation & Set-up



Select xFill tab> verify settings according to screenshot below



Home> Wrench icon> GPS

2009 if needed)

Receiver > Setup (password

4

Select OK to return to Configuration page & select System> Setup



7

Select OK to return to the Configuration page & select GPS receiver & Diagnostics





Select Ag Remote





Scroll down & select Port setup> Setup





Ag Remote Setup instructions

Right arrow twice to Configuration> Down arrow to Configuration menu> Right arrow to Port D config> Down arrow to Enter

Right arrow once to select TSIP & Up arrow to change TSIP to RTCM

\*Confirm Baud rate is set to 38k4> Right arrow 5x to the Bottom TSIP & Up arrow to change to NONE

Press Enter (confirm settings according to screenshot)> Esc icon 3x to return to the main screen

Confirm RTK (with capital R) in top left and A:####





Select the EXP-100 serial # from the AG 815 Secondary Serial dropdown

factor lists (	AG5.1	Te 33	0.000000000		
	H53	46-80	Present		
Dealer Part Antigeneets					
TH JOB COunted Rot	-	18	200 Port A and Port B	-	
EN SH +5	ne are	1	RES Secondary Serial	1112400034	>
E47-108-42	-	- Po	nary USB Part	a dash	
EN IN AL	5. WT	4 n 2 n	113 Secondary Serial International Second	an dank	
Garcel				OK.	

